U.S. Department of Transportation

800 Independence Ave., S.W. Washington, D.C. 20591

Federal Aviation Administration

**Transmittal Letter 15-16** 

June 19, 2015

## PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53 (AVAILABLE ON THE WEB AT HTTP://NFDC.FAA.GOV)

The enclosed Standard Instrument Approach Procedures, Departure Procedures/Takeoff Minimums and Fix Actions are effective as indicated.

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows: EFFECTIVE UPON PUBLICATION

	AIRAC	STATE	CITY	AIRPORT	FDC	FDC	SUBJECT
	DATE				NUMBER	DATE	
	23-Jul-15	ОН	Jackson	James A Rhodes	5/0681	6/9/2015	RNAV (GPS) RWY 1, Amdt 1B

FDC **5/0681** I43 IAP JAMES A RHODES, JACKSON, OH. RNAV (GPS) RWY 1, AMDT 1B... CHART NOTE: PROCEDURE NA AT NIGHT. CHART NOTE: HELICOPTER VISIBILITY REDUCTION BELOW 1 SM NOT AUTHORIZED. DELETE NOTE: VDP NA WITH GREATER PORTSMOUTH ALTIMETER SETTING. DELETE VDP.

THIS IS RNAV (GPS) RWY 1, AMDT 1C. 1506021246-PERM